



1.




2.




3.



4.



5.



6.



7.



8.



9.



10.



11.




12.



13.




14.



15.



16.




17.




18.



19.




20.



21.




22.




23.



24.




25.




26.




27.



28.




29.



30.




31.




32.




33.



34.




35.



36.


vrták Ø 4,1 mm

BC 95-110




vrták Ø 6,8 mm

37.



fréza Ø 25 mm


38.



vrták Ø 4,1 mm


39.

při vrtání tohoto otvoru
nesmí být volící páka
v poloze „R“, nebo „P“
(obr. 39 - 41)




vrták Ø 6,8 mm

40.



vrták Ø 10 mm


41.




42.




43.




44.




45.




46.



47.




48.




49.



50.




51.




52.




53.




54.



55.



56.



57.



58



59



60




61




62




63



64



65



66



