



1



2



3



4



5



6



7



8



9





10



11



12



13



14



15



16



17




18





19



20



21



22




23



24



25



26



27






28




29



30



31




32




33



34



35



36



37




Dle obrázku vyfrézujte otvor

38



Fréza Ø 39,5 mm  
(BF11+BF03)

39



40



41



Fréza Ø 37 mm  
(BF02+BF03)

42





43



43



45