



1.



2.



3.



4.



5.



6.



7.



8.



9.



10.



11.




12.



13.



14.



15.

**РАЗМЕТИТЬ ОТВЕРСТИЕ**



16.



17.

**ПРОСВЕРЛИТЬ ОТВ. Ø 6mm**



18.

**ФРЕЗА ДЛЯ МЕТАЛА ВР 11 Ø 22**





19.



20.



21.



22.



23.



24.